



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

April 24, 2007

Supervisor DRH

**Mine Name:** Temple Strike Quarry  
**Operator Name:** William Day

**Permit number:** S/039/015  
**Inspection Date:** April 5, 2007  
**Time:** 4:00 pm

**Inspector(s):** Lynn Kunzler, DOGM  
**Other Participants:** William Day  
**Mine Status:** Active

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls,
8. Soils
9. Revegetation

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Routine inspection while in the area.

#### Inspection Summary:

This notice was accepted October 2, 2001 and has been active each year since then. Permit fees are current. The Operator has not provided a reclamation surety or reclamation contract for this site. Upon arrival at the site, it appeared as if the 5-acre limit for a small mining operation had been exceeded. A gps was used to survey the disturbed area.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

The results of the GPS survey showed 4.7 acres of disturbance. It is not anticipated to expand in the near future.

CO # MC 07-01-02 was issued for failure to provide or maintain a reclamation surety. Abatement requires the operator to provide an acceptable form of surety in the amount of \$20,700 and a reclamation contract. The operator was told that the only activity that would be allowed until the CO was abated was reclamation or safety maintenance. The appeal process was reviewed with the operator. The operator indicated that he would contact his bank the next day and have them coordinate with Beth Ericksen of the Division in establishing the reclamation surety.

**Inspector's Signature**

LK:pb

O:\M039-Sanpete\S0390015-Templestrike\inspections\Insp-04052007.doc